


**Report of Noise, Dust, and Blasting Monitoring
Vulcan Materials Company
Maryville Quarry**

Blast Date	Time	Seismograph Located on the Quarry Property (MontvaleRd)		Seismograph Located at 2020 Duncan Rd	
		PPV	dB	PPV	dB
1/13/2025	16:16	0.055	109.9	0.04	113.8
1/24/2025	11:23	0.065	110.2	NT	NT
1/31/2025	11:06	NT	NT	NT	NT
2/7/2025	12:23	NT	NT	NT	NT
2/12/2025	11:48	0.055	108.8	NT	NT
2/25/2025	12:50	0.035	114.4	NT	NT
2/28/2025	11:28	NT	NT	NT	NT
3/5/2025	12:14	0.05	112.6	NT	NT
3/11/2025	14:21	NT	NT	0.04	106
3/14/2025	14:25	NT	NT	NT	NT
3/24/2025	14:09	NT	NT	NT	NT
4/2/2025	12:06	0.06	118.6	NT	NT
4/7/2025	13:06	0.065	112.6	NT	NT
4/24/2025	12:30	0.075	106.6	NT	NT
4/30/2025	13:34	0.055	112.6	NT	NT
5/9/2025	13:34	NT	NT	NT	NT
5/13/2025	14:09	NT	NT	NT	NT
5/22/2025	13:10	0.045	115.7	NT	NT
6/2/2025	15:23	0.04	115.2	0.035	114.2
6/11/2025	12:19	0.04	120.2	NT	NT
6/24/2025	11:49	0.06	116.1	NT	NT

*N/T = Seismograph not triggered (PPV levels below detection level of seismograph)

Maryville Quarry Blasting 2025



Maryville Quarry Blasting 2025

