


Report of Noise, Dust, and Blasting Monitoring
 Vulcan Materials Company
 Maryville Quarry

2024 Maryville Quarry Blasting Monitoring

Blast Date	Time	Seismograph Located on the Quarry Property (MontvaleRd)		Seismograph Located at 2020 Duncan Rd	
		PPV	dB	PPV	dB
1/29/24	15:32	NT	NT	0.07	102
2/8/24	13:52	0.25	116	0.07	124
2/9/24	14:06	NT	NT	0.04	109
3/18/24	13:06	0.04	110	0.04	117


*N/T = Seismograph not triggered (PPV levels below detection level of seismograph)

Maryville Quarry Blasting 2024



◆ Seismograph on Quarry Property ■ Seismograph at Garland Residence

Maryville Quarry Blasting 2024



◆ Seismograph on Quarry Property ■ Seismograph at Garland Residence