


Report of Noise, Dust, and Blasting Monitoring  
 Vulcan Materials Company  
 Maryville Quarry

2022 Maryville Quarry Blasting Monitoring

Blast Date	Time	Seismograph Located on the Quarry Property (MontvaleRd)		Seismograph Located at 2020 Duncan Rd	
		PPV	dB	PPV	dB
1/13/22	11:23	0.04	107	0.04	114
2/3/22	12:00	N/T	N/T	0.04	104
2/9/22	12:17	0.04	115	0.06	111
3/1/22	11:32	N/T	N/T	0.05	108
3/8/22	11:16	0.07	105	0.05	115
3/17/22	11:55	0.06	108	0.05	113
3/22/22	10:51	0.04	111	NT	NT
3/29/22	12:30	0.11	110	0.07	112

\*N/T = Seismograph not triggered (PPV levels below detection level of seismograph)

# Maryville Quarry Blasting 2022



◆ Seismograph on Quarry Property      ■ Seismograph at Garland Residence

# Maryville Quarry Blasting 2022

