

Report of Noise, Dust, and Blasting Monitoring  
 Vulcan Materials Company  
 Maryville Quarry

2022 Maryville Quarry Perimeter Noise and Dust Surveys

Sample Location	Latitude	Longitude	Date	Start Time	End Time	Avg. Wind Speed (mph)	Wind Direction	% Cloud Cover	Sound Level (15 min. avg. dB)	Fugitive Dust Observed (Y or N)
#1 Water Tower	N35 43 58.8	W83 57 01.8	3/17/2022	8:48	9:03	5	SSW	75	55.2	N
#2 Milligan Rd	N35 43 40.1	W83 56 46.2	3/17/2022	9:08	9:23	5	SW	75	56.2	N
#3 Eastover	N35 43 30.4	W83 57 18.4	3/17/2022	9:29	9:44	6	SW	75	49.6	N
#4 Trotwood	N35 43 43.3	W83 57 35.8	3/17/2022	9:51	10:06	7	SSW	60	61.7	N
#5 Montvale Rd	N35 43 53.8	W83 57 53.7	3/17/2022	10:12	10:27	8	SSW	40	56.7	N
#6 Soccer Field	N35 44 17.3	W83 57 13.4	3/17/2022	10:57	11:12	7	SW	40	59.1	N

# Maryville Quarry Noise Monitoring 2022

